

03500.015833



PATENT

Copy A

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)
TETSUYA KANEKO, ET AL.)
Application No.: 09/960,744)
Filed: September 24, 2001)
For: METHOD OF MANUFACTURING)
IMAGE DISPLAY APPARATUS)
U.S. Patent No. 6,821,174 B2)
Issued: November 23, 2004)

Examiner: M. Santiago

Group Art Unit: 2879

**Certificate
MAR 16 2005
of Correction**

The Honorable Commissioner of Patents
and Trademarks
P.O. Box 1450
Alexandria, VA 22313-1450

**RECEIVED
MAR 18 2005
OIPE/JCIVS**

**REQUEST FOR
CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes and mistakes which are not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

03/18/2005 EABUBAK1 00000141 6821174

01 FC:1811


100.00 DP

MAR 25 2005

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,



Attorney for Patentees
Scott D. Malpede
Registration No. 32,533

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SDM:nnn

DC_MAIN 191411v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,821,174 B2

DATED : November 23, 2004

INVENTOR(S) : TETSUYA KANEKO, ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6:

Line 32, "atmosphere" should read --atmosphere--.

Line 65, "the-voltage" should read --the voltage--.

COLUMN 18:

Line 8, "connected/boded" should read --connected/bonded--.

DC_MAIN 191408v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,821,174 B2

No. of add'l. copies
@ 30¢ per page

MAR 25 2005

→

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,821,174 B2

DATED : November 23, 2004

INVENTOR(S) : TETSUYA KANEKO, ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6:

Line 32, "atmosphere" should read --atmosphere--.

Line 65, "the-voltage" should read --the voltage--.

COLUMN 18:

Line 8, "connected/boded" should read --connected/bonded--.

DC_MAIN 191408v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,821,174 B2No. of add'l. copies
@ 30¢ per page

MAR 25 2005

